



GARY R. HERBERT
Governor
SPENCER J. COX
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Minerals Inspection Report

Reviewed

[Signature]

Report Date: 05/17/2016

Mine Name: Westlake Pit	Permit Number: S/49/0090	Mine Status: Inactive
Operator Name: Westlake Materials LLC	Inspection Date: 05/17/2016	Permit Fees: Delinquent
Inspector(s): A. Abate	Inspection Time: 10 AM	Bond Amount: \$55,100
Attendee(s): None	Weather: Cloudy 60s	Bond Escalation: 1/18/2018
Inspection Purpose: Verify whether or not the site was ever disturbed		Prior Inspection: None

Conclusions and Recommendations

No mining activity was observed during this inspection. Withdrawal of the small mine permit notice is recommended.

Elements of Inspection		Evaluated & Commented	Enforcement
1.	Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Permit fee has not been paid. Operator correspondence has been returned. Site is considered abandoned. The Division received a bond cancellation notice from the bond company. This inspection was to confirm whether or not any mining activity ever occurred on site. No mining activity was observed during this inspection.			
2.	Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>
3.	Protection of Drainages/Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>
4.	Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>
5.	Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>
6.	Reclamation	<input type="checkbox"/>	<input type="checkbox"/>
7.	Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>
8.	Soils	<input type="checkbox"/>	<input type="checkbox"/>
9.	Revegetation	<input type="checkbox"/>	<input type="checkbox"/>
10.	Other	<input type="checkbox"/>	<input type="checkbox"/>

Inspector's Signature:

[Signature]

CC: Waidd Co (South) LP, 1468 North 450 East, Pleasant Grove, UT 84062
Peggy Kelsey, Utah County, peggyk@utahcounty.gov

File: /nrwogmfs1/OGM/GROUPS/MINERALS/WP/M049-Utah/S0490090-WestlakePit/inspections/Insp-5-17-2016.pdf





View of the outcrop in the permit area from Highway 68 looking northwest.



View from the top of the outcrop looking down at the road facing southeast.



View from midway up the hill showing the shallow outcroppings of rock.



View of the hillside looking west.

WestLake Pit Mine S/49/0090

